

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 26

Dated: 27.02.2024

It is certified that the existing building **SARASWATI SHISHU VIDYA MANDIR** (name of the building or premises) at **DHURWA, RANCHI - 4 (JHARKHAND)** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<b>G + 2</b>	<b>G + 2</b>	<b>G + 1</b>	<b>G + 1</b>		

The building is owned / occupied by **SARASWATI SHISHU VIDYA MANDIR** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **BUILDING DIVISION 1, RANCHI** (Name of Department / Govt.) on **27.02.2024** (date of inspection) in the presence of **Sri AKHILESHWAR NATH MISHRA, SECRETARY** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **27.02.2024** for a period of **03** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural Safety of School Building
2. Earthquake Management
3. Electrical Safety
4. Playground and Laboratory Safety

Issued on **27.02.2024** at **DHURWA** by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : \_\_\_\_\_

Name : **GANESH KUMAR**

Designation : **ASSISTANT ENGINEER - 1, बरियार**

Name & Address of Department/ Office: **BUILDING DIVISION 1, RANCHI, JHARKHAND**

**MANAGER**

**Saraswati Shishu Vidya Mandir  
Dhurwa, Ranchi-834004**

**Principal**

**Saraswati Shishu Vidya Mandir - 2  
CBSE AFF No.-3430123, School No.-66320  
Dhurwa, Ranchi-834004 (Jharkhand)**